

Technical Service Bulletin					
Edition: Final V2	TSB#: 368 (ECR1683/1797)	Issue date: May 06, 2022	Page 1 of 3		

Title: Thermal Cut Out update to meet new standard.

	OLD Part – no longer available:	NEW Part – now available:	For Machine Types:
	10200141_Thermal_Cut out_1_Pole	60700000_Thermal_Cut-out_1_Pole	EX3 / ONYX / G-10 / ROSETTA / MEGACREM / NEW ELEGANCE / MONROC / ZIRCON / CARAT
1 POLE THERMOSTAT	20010051_Support_REV02 (for thermostat PN10200141)	20010059_Support_REV01 (for thermostat 60700000)	ONYX / G-10/ ROSETTA / MEGACREM / NEW ELEGANCE / MONROC / ZIRCON / CARAT
	-	76100020_Kit_Thermal_Cut- out_1_Pole	Spare parts kit (Thermal cut-out + bracket)
3 POLE THERMOSTAT	10200150_Thermal_Cut_3_Pole	1660194-Thermal_Cut-Out_3_Pole	ALL 3 Phase version machines of: DIAMANT PRO / EX3 / G-10 / NEW ELEGANCE / MONROC / ONYX PRO / ZIRCON

#### Applies to machine types:

## 1 POLE THERMOSTAT change:

• EX3/ONYX/G-10/ROSETTA/MEGACREM/NEW ELEGANCE/MONROC/ZIRCON/CARAT

#### 3 POLE THERMOSTAT change - ALL 3 Phase version machines of:

• DIAMANT PRO / EX3 / G-10 / NEW ELEGANCE / MONROC / ONYX PRO / ZIRCON

#### Implemented from first serial number:

#### 1 POLE THERMOSTAT change:

- Legacy: PN60700000\_&\_PN20010059\_SN62102695 (2021-11-04)
- EX3: PN60700000 SN62102709 (2021-11-04)

## 3 POLE THERMOSTAT change:

PN1660194\_from\_SN02203600 (2022-05-04)

#### **Change information:**

Due to an update of the compliance standard, a new model that meets with trip-free new requirements will be implemented: PN60700000 for 1 Pole and PN1660194 for 3 pole machines.

[1 POLE]: PN607000000, requires new support bracket. Kit for field has been created. See following page.

[3 POLE]: Backwards compatible. (Fixed to chassis).

### **Backward compatibility:**

[1 POLE]: Not compatible as new thermostat requires new support bracket. (Kit can be ordered)

[3 POLE]: Backwards compatible.

#### Machines in the field:

For machines in the field, require no change.

#### Warranty information:

No warranty changes.

#### **Spare part information:**

[1 POLE]: A kit PN76100020 can be ordered as spare part for machines with old 1 pole thermostat. For machines with new thermostat and support, the kit is not needed. Order only the thermostat. [3 POLE]: New part can be ordered and it's totally compatible.



Technical Service Bulletin					
Edition: Final V2	TSB#: 368 (ECR1683/1797)	Issue date: May 06, 2022	Page 2 of 3		

## Improvement descriptions:

#### **THERMOSTAT 1 POLE:**



## **THERMOSTAT 3 POLE:**






Technical Service Bulletin					
Edition: Final V2	TSB#: 368 (ECR1683/1797)	Issue date: May 06, 2022	Page 3 of 3		

# Kit Information and Instruction for 1 POLE THERMOSTAT


As new thermostat is not backwards compatible with old support: This kit has been created including new thermostat and new support.

#### Kit contains:



## For machines in the field, this kit can be ordered for:

- Legacy machines with previous SN than: SN62102695 (2021-11-04) (ONYX/G-10/ROSETTA/MEGACREM/NEWELEGANCE/MONROC/ZIRCON/CARAT)
- EX3 with previous SN than: SN62102709 (2021-11-04).



#### EX3 now:

(Order ONLY the new thermostat PN60700000, as the support is included in the chassis.)

